



SOT-32 (TO-126)



P032-7

(1) Within this region the cross-section of the leads is uncontrolled