

$S = 0,4 \text{ mA/V}$
 $\mu = 40$
 $R_i = 100 \text{ k}$
 $P_a = \text{max. } 0,1 \text{ W}$

