

$S = 3.2 \text{ mA/V}$   
 $V_{g1} = -11\text{V}$   
 $R_i = 90\text{k}$   
 $W_a = 6\text{Wmax.}$

