


$S=11,3\text{mA/V}$
 $V_{g1}=-7,3\text{V}$
 $R_i=38\text{k}$
 $P_a=\text{max. } 12\text{W}$



$S=10.4\text{mA/V}$
 $V_{g1}=-6.4\text{V}$
 $R_i=40\text{k}$

